
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-285	Smoke	9/9/2009	ADS/TM	S09II1008MH	Dry	Yes	874.46

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11II1030G1	S11II1030MH	S11II1010MH	58.8528	18
S11II1010G1	S11II1010MH	S11II1019MH	71.6213	18
S09II1008G1	S09II1008MH	S11II1010MH	108.611	8
S09II1017G1	S09II1017MH	S09II1008MH	635.371	8

Observations & Photos

Obs_ID S1028-285-OB01

Address 4624 Reisterstown Rd

Status Private

Source Service Lateral

Location Yard - front

Nearest MH S09II1008MH

Comments Smoke from service lateral in front yard. 4624 Reisterstown Rd.



Picture \S1028-285-OB01-P01.jpg

Comments Front of house, 4624 Reisterstown Rd.

Obs_ID S1028-285-OB02

Address 4642 Reisterstown Rd

Status Private

Source Service Lateral

Location Yard - front

Nearest MH S09II1017MH

Comments Smoke from service lateral in front yard. 4642 Reisterstown Rd.



Picture \S1028-285-OB02-P01.jpg

Comments Front of house, 4642 Reisterstown Rd.